

City of Murray Lockout Tagout Procedures

Machi				F	Plant: Wastewater Treatment Plant				
Area:	North East		odated:	7/9/10	_				
Pers	sonal Protective	e Equipment:	CENE CONTRACTOR	Corner Corner					
Sa	Safety Glasses Steel Toe Shoes		Leather Gloves (as needed)		Nitrile Gloves (as needed)				
SAFE	OPERATING P	ROCEDURES:							
 Always Lock, Tag, and Try to control hazardous energy sources prior to performing maintenance or service on this machine, when removing or bypassing a guard, and/or under any circumstance where the unexpected start-up or energization of the equipment could cause bodily harm. 				be of 3. This syst	 If works need to be done to prop, winch boom must be cranked forward till prop is visible. This machine can be turned off by the cannibal system computer, but shall be locked out at breaker. 				
(Use tl energy	may cause injury. (i.e	DURE: ny servicing or maintenance act e. repairs, set-up, clearing parts quipment Needed:		performed where to	he expecte	ed energization, start	up, or relea	ase of stored	
		DANCER Was a for the second of the second o							
	Lock		asp						
Before Servicing or Maintenance:									
2. C m 3. Ic	agout the equipmer lear the area and e naterials. dentify Interchange outheast side of the enter of the control	quipment of tools, parts a Mixer 1 knife switch on the Filter Press Building in the	*NOTE* person/ done. 6. Dissipations beside v						
Ene	ergy Sources:	11							
	Magnitude:	460V							
Ener	gy Isolation Device & Location:	Control Panel in Filter Press Building							
After	Servicing or M	I	I		I		1		
1. Ve 2. CI 3. M. 4. No er 5. Re	Verify all controls are "off" or in neutral position. Clear machine or equipment of tools, parts, or people. Make sure all guarding is in place. Notify affected personnel that the machine or equipment will be reenergized. Remove locks, devices, and tags from energy isolation devices.				pared by: Date: 7/9/10				
	devices to normal operating position.								